



Technical Note
Wi-Fi CERTIFIED Miracast™ HDCP
Interoperability Issue:
HDCP 2.2 Protocol Descriptor
Version 1.0
March 24, 2015

WI-FI ALLIANCE PROPRIETARY – SUBJECT TO CHANGE WITHOUT NOTICE

This document may be used with the permission of Wi-Fi Alliance under the terms set forth herein.

By your use of the document, you are agreeing to these terms. Unless this document is clearly designated as an approved specification, this document is a work in process and is not an approved Wi-Fi Alliance specification. This document is subject to revision or removal at any time without notice. Information contained in this document may be used at your sole risk. Wi-Fi Alliance assumes no responsibility for errors or omissions in this document. This copyright permission does not constitute an endorsement of the products or services. Wi-Fi Alliance trademarks and certification marks may not be used unless specifically allowed by Wi-Fi Alliance.

Wi-Fi Alliance has not conducted an independent intellectual property rights ("IPR") review of this document and the information contained herein, and makes no representations or warranties regarding IPR, including without limitation patents, copyrights or trade secret rights. This document may contain inventions for which you must obtain licenses from third parties before making, using or selling the inventions.

Wi-Fi Alliance owns the copyright in this document and reserves all rights therein. A user of this document may duplicate and distribute copies of the document in connection with the authorized uses described herein, provided any duplication in whole or in part includes the copyright notice and the disclaimer text set forth herein. Unless prior written permission has been received from Wi-Fi Alliance, any other use of this document and all other duplication and distribution of this document are prohibited.

Unauthorized use, duplication, or distribution is an infringement of Wi-Fi Alliance's copyright.

NO REPRESENTATIONS OR WARRANTIES (WHETHER EXPRESS OR IMPLIED) ARE MADE BY WI-FI ALLIANCE AND WI-FI ALLIANCE IS NOT LIABLE FOR AND HEREBY DISCLAIMS ANY DIRECT, INDIRECT, PUNITIVE, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES ARISING OUT OF OR IN CONNECTION WITH THE USE OF THIS DOCUMENT AND ANY INFORMATION CONTAINED IN THIS DOCUMENT.



Introduction

HDCP is a content protection mechanism that governs the transfer of media between devices that originate protected content (Sources) and displaying devices (Sinks). A common use case is a Miracast® user displaying an HDCP-protected movie from their mobile phone or tablet to a television.

This document describes an observed interoperability issue between some Miracast Source implementations with an HDCP 2.0/2.1 stack/certificate and some Miracast Sink implementations with an HDCP 2.2 stack/certificate where the content does not render correctly due to an authentication issue. If a Source fails authentication with a Sink, the user may experience errors such as:

- The Source and Sink may provide no information to the user, and it appears to the user that the connection has “failed”
- The Source may provide an audio-only connection to the Sink
- The Source may show a blank screen to the user with no other information
- The Source or Sink may indicate some kind of “Content Protection” error

Problem

Some Source implementations incorrectly assumed that Reserved bits (3087:3072) in the HDCP Receiver Public Key Certificate of [1] must always be zero (0x0000) and rely on that assumption as part of signature validation. HDCP 2.2 updated the certificate format and uses 4 of the 16 previously reserved bits (3087:3084) as the Protocol Descriptor [2], The Protocol Descriptor value can be 0x0 or 0x1. If the Source fails signature validation for Sinks supplying a certificate as part of AKE_RX_Info message of [1] with the bits set to anything other than 0x0, then it will not authenticate Sinks using HDCP 2.2 certificates, resulting in broken forward compatibility.

Similar problems may occur if an HDCP capable Sink inadequately handles the received Reserved bits within HDCP AKE messages of [2] from a Source.

Recommendation

Wi-Fi Alliance® recommends that all HDCP-capable Miracast device vendors check their devices for implementations that inadequately handle the received Reserved bits defined in the HDCP IIA 2.x specification and update any affected devices to correct this error. All 16 bits (3087:3072) shall be ignored in HDCP 2.0/2.1 implementations and the specific bits of the Protocol Descriptor shall be checked in HDCP 2.2 implementations (3087:3084).

Suggestions on providing feedback to a user after an authentication error are described in the “Best Practices Document for Wi-Fi CERTIFIED Miracast™ Devices” [3].



References

- [1] [“High-bandwidth Digital Content Protection System, Interface Independent Adaptation” Revision 2.0](#), 23 October, 2008, [Digital Content Protection LLC](#)
- [2] [“High-bandwidth Digital Content Protection System, Interface Independent Adaptation” Revision 2.2](#), 16 October, 2012, [Digital Content Protection LLC](#)
- [3] [“Best Practices Document for Wi-Fi CERTIFIED Miracast™ Devices”](#), September 2014, [Wi-Fi Alliance](#)